

Joint Deterioration Causes and Solutions


KU Asphalt Conference 2023



Ross Weber | KU Conference 2023




Presentation objectives



The majority of longitudinal cracks are caused by stripping.

- Longitudinal joints deteriorate due to stripping.
- Top-Down Longitudinal Cracks are caused by stripping.
- Both commonly occur within a two-foot band.
- Both can be a source of water infiltration and can feed water between the two.



Phrases to remember:



Water Pathways




Density Dams



Connecting Voids

NCAT research indicates 12.5 mm mixes are permeable at 7 to 8 % in place air voids

Figure 3. In-place air voids vs. permeability (NCAT).



Most pavements look good in the beginning



With enough time most will look like this



The damage is already done

Ross Weber | KU Conference 2023

What is a primary joint crack?

Interface between first and second pass of paver

- Damage at the joint caused by roller
- Low Density
- Poor drainage
- Mix prone to stripping
- Matching to tight



Primary joint crack

Interface between first and second pass of paver

- Damage at the joint caused by roller
- Low Density
- Poor drainage
- Mix prone to stripping
- Matching to tight



Primary joint crack

Interface between first and second pass of paver

- Damage at the joint caused by roller
- Low Density
- Poor drainage
- Mix prone to stripping
- Matching to tight



Primary joint crack

Interface between first and second pass of paver

- Damage at the joint caused by roller
- Low Density
- Poor drainage
- Mix prone to stripping
- Matching to tight



Primary joint crack

Interface between first and second pass of paver

- Damage at the joint caused by roller
- Low Density
- Poor drainage
- Mix prone to stripping
- Matching to tight



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack



- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe




Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack

- Secondary Joint Crack (Near Joint)
 - Damage near joint caused by roller
 - Low density
 - Poor drainage
 - Mix prone to stripping
 - Irregular density caused by screed set-up
 - Edge of Stripe



Secondary joint crack



Compacting Joint



Secondary joint crack





Becomes more
obvious as binder
ages

Ross Weber KU Conference 2023

Stays wet longer than the roadway



Longitudinal and transverse – Note different look



Secondary joint crack



Roller turn damage in paved surface



Roller turn damage in milled surface



Rumble strips
make roads
much safer



Are rumble strips a maintenance problem?

They are likely a necessary problem



Ross Weber | KU Conference 2023

Stands water long
after the roadway
is dry





Why dry cut in
middle of
wet?



Pocket of
segregation
drained
individual cut





Extremely wet to
extremely dry
within same section



Wet beside stripe

- Dried quickly between stripes
- Rumbles with stripe stayed wet
- Stripe is directly over the joint
- I questioned if there was room, even in a poor joint, for the amount of water that disappeared.

Top & bottom of core over roller mark.

- There are a lot of voids in the bottom of most cores.
- There is potential to store and move water from the substrate.
- The bottom surface of this core easily absorbed 8 ml of water (13 oz/sqy)

Is loading fatigue a problem?

- In my opinion it is not normally an issue
- Cracks occur in the absence of traffic.


How do we know fatigue isn't the problem?

- If fatigue were the issue, we should not find cracks in areas with little loading, such as gore areas and dead lanes.

How do we know fatigue isn't the problem?

- If fatigue were the issue, we should not find cracks in areas with little loading, such as gore areas and dead lanes.
- Cracks should follow the path traffic takes
- They always follow the path of the paver and rollers.

Cores of roller marks



Top of core is severely damaged



Ross Weber | KU Conference 2023

Note damage in top 1"









Ross Weber | KU Conference 2023



Ross Weber | KU Conference 2023







Centerline core

- Some voids in top $\frac{3}{4}$ " at center line
- Open texture on top right
- Excellent density

Centerline core


- Smooth on left rough on right
- Joint is tight
- Weighed up at 93%+ density





Water can come through the
bottom of the lift


Brine from below found
the pathways in a new
overlay resulting in early
failure



Same pattern as
the brine photo



US-77 2018




July 2019 1/2" mill 1 1/2" overlay 12.5A



Playback Delay (4) Step Increment (1 Frames) Play & Step Controls Downward Image Offset Downward Image

Int In/O Rng Rng/O - 0 +



2020



Navigation and control interface including playback buttons (stop, play, fast forward, fast reverse), a search icon, a refresh icon, a print icon, a back arrow, and a menu. On the right, there are camera selection buttons: 'Int', 'In/O', 'Rng', 'Rng/O', a zoom out button (-), a zoom level indicator '0', and a zoom in button (+). A small orange car icon is positioned above the main video frame.



2023



Playback Delay (4) Step Increment (1 Frames)

Play & Step Controls

Downward Image Offset Downward Image

Int Int/O Rng Rng/O - 0 +






Roller turnout should be limited

The head of material from the left doesn't belong on the right.



Short or no turnout
keeps mix where it
belongs



Roller turn out damages the mix





Obviously, roller marks that create cracks

Density can be great and fall at the joint









Raised extension to improve joint density




This may improve the joint at the expense of the wheel path

Raising extensions moves the density problem
Any crown within a lane creates density problems





Elevated extension &
rolling inside of edge



Most centerlines are paved nearly flat



What are we going to do about it?

Mastic over sinusoidal rumble strips



Ross Weber | KU Conference 2023

Sinusoidal with crack after a year





Mastic over conventional rumble strips

Open crack even with mastic applied






J-Band



Avoid
roller
marks as
much as
possible



Eliminate
mixes that
strip




Uniform
Density



Raising extensions
moves the density
problem

Any crown within a lane
creates density
problems



Lower Air
Voids



Training is difficult

J-Band on bottom

Mastic on Top

Uniform Density

Proper Amount of Slope

Roller Marks

Flat Screed

Eliminate Stripping

Lower Va



Questions